

**Customer Advice Note
CAN #133**

**E080-10, A083-00-10
Firmware update v4.14**

Date: February/2021

Introduction

This Customer Advice Note details a firmware update for the Honeywell Galaxy Ethernet Modules as part of our commitment to on-going product improvements.

This document describes the changes between v4.11 and v4.14 .

Availability

The new firmware has been released to our manufacturing facility for general production.

Field upgrades:

Note: Due to cyber security, field upgrades via MAXPRO CLOUD and or the Flash Programmer are not permissible.

Products

E080-10, A083-00-10

Identification

Note : Ensure the product packing label refers to SW1 : 4.14 (firmware version 4.14) and / or QR code has manufacturing date February 2021 onwards.

Scanned QR code example

100-06932A;B1D400121B50;**200325**;426

xxxxxxxx;xxxxxxxxxxx;**date code**;xxx

Key Features Released

- Cyber Security Updates.
- New Galaxy User Management, Timed Set available via MAXPRO CLOUD.
- IB2 Fix Galaxy Flex.
- RS485 Communication Error fix.
- Reduced the application's CPU usage in top from 99% to around 12%.
- Ethernet Module Boot Time reduced with Galaxy Dimension.
- Incorrect IP address fix.
- Opensource libraries update.
- Integration updates.
- Event reporting fix (Comm Fail).

Impact

Hardware	y
Remote Routing Inspection	n
Standards and Legislation	n
Part Numbers Affected	y

Miscellaneous Changes	y
Signaling Changes	n
Technical Changes	y
Programming	n