

**Version 6.x firmware panels must use V7.0 PS Tools for proper functionality.**

Prior to performing a firmware updates it is **MANDATORY** that you upload the program using PS Tools before performing any updates; especially the MS-9200UDLS 5.x to 6.x, and the MS-9600LSUDLS 4.x to 6.x.

The procedure should be as follows:

1. Update the PS Tools to version 7.x
2. Upload the panel. (This way in the event that the program is corrupted by the update you will have a copy that is compatible with PST 7.x to download into the updated panel that requires 7.x.)
3. Update the firmware as normal using PPU Wizard 3.4.1

If the panel reboots and returns a “CS CALC FAULT”, a RESET of the panel should clear it.

[Download the 9200UDLS62B1.zip](#)