

*******Important Notification to Installer – MUST READ*******

It is your responsibility to confirm the system on which this expander is being installed has the appropriate upgraded firmware. The MS-9600(UD)LS/ Unimode9600(UD)LS series panel must have version 4.3 or higher firmware installed for proper operation. Check the www.firelite.com website for the appropriate firmware version for this hardware revision.

****Failure to properly upgrade the panel firmware may ultimately result in the system becoming inoperable without a reported alarm or trouble condition****

Instructions for verifying panel firmware version or upgrading panel firmware may be found in the panel manual which is available at www.firelite.com.

53828:A 4/6/2010 10-214

*******Important Notification to Installer – MUST READ*******

It is your responsibility to confirm the system on which this expander is being installed has the appropriate upgraded firmware. The MS-9600(UD)LS/ Unimode9600(UD)LS series panel must have version 4.3 or higher firmware installed for proper operation. Check the www.firelite.com website for the appropriate firmware version for this hardware revision.

****Failure to properly upgrade the panel firmware may ultimately result in the system becoming inoperable without a reported alarm or trouble condition****

Instructions for verifying panel firmware version or upgrading panel firmware may be found in the panel manual which is available at www.firelite.com.

53828:A 4/6/2010 10-214