

Fire-Lite Alarms

1 Fire-Lite Place Northford, CT 06472 www.firelite.com

Fire-Lite Alarms SWIFT® Tools 4.1 Release Notes

This Fire-Lite SWIFT firmware suite contains the latest version of SWIFT Tools (version 4.1), wireless gateway application files, device application files and the W-USB application file.

The SWIFT Tools 4.1.zip folder contains the following files:

- SWIFT Tools.exe
- SWIFT 4.1 Release Notes
- SWIFT Installation Quick Start Guide
- SWIFT Link Test Quick Start Guide
- SWIFT Site Survey Quick Start Guide

SWIFT Tools version 4.1 provides the following fixes and modifications:

- System upgrades
 - Enhanced cybersecurity functionality
 - Ability to disable max gateway trouble reporting based on testing procedures outlined in installation manual
 - o Firmware version 1.0 removed from SWIFT Tools for all future releases
- Low frequency sounder and sounder strobe compatibility
 - Wireless addressable wall-mounted (WAV-RL/WAV-WL) and ceiling-mounted (WAV-CRL/WAV-CWL)
 AV bases are now compatible with System Sensor L-Series low frequency sounder and sounder strobe notification appliances
 - SWIFT systems running firmware version 4.1 and higher will be able to properly display low frequency sounders as differentiated from traditional AV devices within SWIFT Tools

IMPORTANT NOTE: All devices within the SWIFT mesh network must be running the same firmware version. Refer to Appendix E, "Firmware Upgrade/Downgrade Instructions" of the SWIFT Gateway Instruction Manual for firmware upgrade instructions. Due to the nature of the cybersecurity updates in SWIFT Tools version 4.1, the individual device firmware update method described in Appendix E.3 "Device and Gateway Firmware Upgrade/Downgrade Procedure" of the manual must be followed.