

Pro-Watch[®] VMS and NVR

Approved Microsoft[®] Windows Patches



Technical Notes

MICROSOFT® WINDOWS PATCHES TESTED WITH PRO-WATCH® NVR AND VMS

Overview

The purpose of this document is to identify the patches that have been delivered by Microsoft® Windows and which have been tested against the current shipping versions of Pro-Watch® NVR and Pro-Watch® VMS with no adverse effects being observed.

If you have questions concerning the information in this document, please contact Honeywell Technical Support. See the back cover for contact information.

Windows Patches Tested with Pro-Watch® NVR till the Month of: December, 2021

Windows Patches Tested with Pro-Watch® VMS till the Month of: December, 2021

This document contains:

Section	See...
<ul style="list-style-type: none"> • December - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2016 Standard • December - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Client on Windows 10 (Enterprise) • December - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise) • December - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2019 Standard 	<p>page 5</p> <p>page 5</p> <p>page 5</p> <p>page 5</p>
<ul style="list-style-type: none"> • November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2019 Standard • November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Client on Windows 10 (Enterprise) • November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise) 	<p>page 6</p> <p>page 6</p> <p>page 6</p>
<ul style="list-style-type: none"> • October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2019 Standard • October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Client on Windows 10 (Enterprise) • October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise) 	<p>page 6</p> <p>page 6</p> <p>page 6</p>
<ul style="list-style-type: none"> • September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard • September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise) • September - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise) 	<p>page 6</p> <p>page 6</p> <p>page 6</p>
<ul style="list-style-type: none"> • August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard • August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise) • August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise) 	<p>page 8</p> <p>page 7</p> <p>page 7</p>
<ul style="list-style-type: none"> • July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard • July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise) • July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise) 	<p>page 8</p> <p>page 8</p> <p>page 8</p>
<ul style="list-style-type: none"> • June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard • June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise) • June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise) 	<p>page 9</p> <p>page 9</p> <p>page 9</p>

Section	See...
<ul style="list-style-type: none"> • <i>May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i> • <i>May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/ Client on Windows 10 (Enterprise)</i> • <i>May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</i> 	<p><i>page 10</i></p> <p><i>page 10</i></p> <p><i>page 10</i></p>
<ul style="list-style-type: none"> • <i>April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i> • <i>April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/ Client on Windows 2016 Standard and Windows 10 (Enterprise)</i> • <i>April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</i> 	<p><i>page 11</i></p> <p><i>page 11</i></p> <p><i>page 11</i></p>
<ul style="list-style-type: none"> • <i>March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i> • <i>March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</i> • <i>March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</i> 	<p><i>page 12</i></p> <p><i>page 12</i></p> <p><i>page 12</i></p>
<ul style="list-style-type: none"> • <i>February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i> • <i>February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</i> • <i>February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</i> 	<p><i>page 13</i></p> <p><i>page 13</i></p> <p><i>page 14</i></p>
<ul style="list-style-type: none"> • <i>January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i> • <i>January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</i> • <i>January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</i> 	<p><i>page 14</i></p> <p><i>page 14</i></p> <p><i>page 15</i></p>

Pro-Watch® NVR Current Shipping Version

- Pro-Watch® NVR Server and Client

Build	Pro-Watch® NVR 6.7 Build 687
Operating System	Microsoft® Windows 10, 64 bit (Standard) Enterprise Server + Client)
SQL Version	Microsoft® SQL Server 2017 (RTM-CU19) (KB4535007) - 14.0.3281.6 (X64)

Pro-Watch® VMS Current Shipping Version

- Pro-Watch® VMS Server and Client

Build	Pro-Watch® VMS R670 Build 687
Operating System	Microsoft® Windows 2016 Standard 64 bit for Server Microsoft® Windows 2019 Standard 64 bit for Server. Microsoft® Windows 10 Enterprise, 32-bit / 64-bit for Client
SQL Version	Microsoft® SQL Server 2017 (RTM-CU19) (KB4535007) - 14.0.3281.6 (X64)

Note: Microsoft will no longer provide security updates or support for PCs with Windows 7.

December - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2016 Standard

Microsoft Knowledge Base Article ID	Description
KB4486129	Microsoft .NET Framework 4.8 for Windows 10 version 1607, Windows 10 version 1703 and Windows Server 2016
KB4535680	KB4535680: Security update for Secure Boot DBX: January 12, 2021
KB4589210	KB4589210: Intel microcode updates for Windows 10, version 1607 and Windows Server 2016
KB5005698	KB5005698: Servicing stack update for Windows 10, version 1607: September 14, 2021
KB5008207	December 14, 2021—KB5008207 (OS Build 14393.4825)
KB5007152	November 9, 2021—KB5007152 Cumulative Update for .NET Framework 4.8 for Windows 10, version 1607 and Windows Server, version 2016

December - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4593175	Servicing stack update for Windows 10, version 2004 and 20H2: December 8, 2020
KB5008212	December 14, 2021—KB5008212 (OS Builds 19041.1415, 19042.1415, 19043.1415, and 19044.1415)

December - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5008218	December 14, 2021—KB5008218 (OS Build 17763.2366)

December - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5008218	December 14, 2021—KB5008218 (OS Build 17763.2366)

November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5007290	November 19, 2021-KB5007290 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5007266	November 22, 2021-KB5007266 (OS Build 17763.2330) Preview

November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5007289	November 19, 2021-KB5007289 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2, and Windows Version 21H1
KB5007253	November 22, 2021-KB5007253 (OS Builds 19041.1387, 19042.1387, 19043.1387, and 19044.1387) Preview

November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5007290	November 19, 2021-KB5007290 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5007266	November 22, 2021-KB5007266 (OS Build 17763.2330) Preview

October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5006366	October 19, 2021-KB5006366 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5006744	October 19, 2021—KB5006744 (OS Build 17763.2268) Preview

October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5005539	October 12, 2021-KB5005539 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2, and Windows Version 21H1
KB5006670	October 12, 2021—KB5006670 (OS Builds 19041.1288, 19042.1288, and 19043.1288)

October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5006366	October 19, 2021-KB5006366 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5006744	October 19, 2021—KB5006744 (OS Build 17763.2268) Preview

September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5005540	September 21, 2021-KB5005540 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5005625	September 21, 2021-KB5005625 (OS Build 17763.2210) Preview

September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5005565	September 14, 2021-KB5005565 (OS Builds 19041.1237, 19042.1237, and 19043.1237)

September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5005540	September 21, 2021-KB5005540 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5005625	September 21, 2021-KB5005625 (OS Build 17763.2210) Preview

August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5005112	KB5005112: Servicing stack update for Windows 10, version 1809: August 10, 2021
KB5005030	August 10, 2021—KB5005030 (OS Build 17763.2114)

August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5004331	August 10, 2021-KB5004331 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2, and Windows Version 21H1
KB5005033	August 10, 2021—KB5005033 (OS Builds 19041.1165, 19042.1165, and 19043.1165)
KB5005260	KB5005260: Servicing stack update for Windows 10, version 2004, 20H2, and 21H1: August 10, 2021

August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5005112	KB5005112: Servicing stack update for Windows 10, version 1809: August 10, 2021
KB5005030	August 10, 2021—KB5005030 (OS Build 17763.2114)

July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5004332	July 20, 2021-KB5004332 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5004424	KB5004424: Servicing stack update for Windows 10, version 1809: July 20, 2021
KB5004308	July 20, 2021-KB5004308 (OS Build 17763.2090) Preview

July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5003537	July 13, 2021-KB5003537 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2, and Windows Version 21H1
KB5000736	KB5000736: Featured update to Windows 10, version 21H1 by using an enablement package
KB5004237	July 13, 2021-KB5004237 (OS Builds 19041.1110, 19042.1110, and 19043.1110)

July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5004332	July 20, 2021-KB5004332 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5004424	KB5004424: Servicing stack update for Windows 10, version 1809: July 20, 2021
KB5004308	July 20, 2021-KB5004308 (OS Build 17763.2090) Preview

June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5003538	June 15, 2021-KB5003538 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5003711	KB5003711: Servicing stack update for Windows 10, version 1809: June 8, 2021
KB5003703	June 15, 2021-KB5003703 (OS Build 17763.2028) Preview

June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4023057	KB4023057: Update for Windows 10 Update Service components
KB4052623	Update for Microsoft Defender antimalware platform
KB890830	Remove specific prevalent malware with Windows Malicious Software Removal Tool (KB890830)

June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5003538	June 15, 2021-KB5003538 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5003711	KB5003711: Servicing stack update for Windows 10, version 1809: June 8, 2021
KB5003703	June 15, 2021-KB5003703 (OS Build 17763.2028) Preview

May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5003255	May 20, 2021-KB5003255 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5003243	KB5003243: Servicing stack update for Windows 10, version 1809: May 11, 2021
KB5003217	May 20, 2021-KB5003217 (OS Build 17763.1971) Preview

May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5003254	May 25, 2021-KB5003254 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2 and Windows 10 Version 21H1
KB4562830	Feature Update through Windows 10, version 20H2 Enablement Package
KB5003173	May 11, 2021-KB5003173 (OS Builds 19041.985, 19042.985, and 19043.985)

May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5003255	May 20, 2021-KB5003255 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB5003243	KB5003243: Servicing stack update for Windows 10, version 1809: May 11, 2021
KB5003217	May 20, 2021-KB5003217 (OS Build 17763.1971) Preview

April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB5001404	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
KB5001342	April 13, 2021—KB5001342 (OS Build 17763.1879)

April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5001404	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
KB5001407	KB5001407: Servicing stack update for Windows 10, version 1809: April 22, 2021
KB5001384	April 22, 2021-KB5001384 (OS Build 17763.1911) Preview
KB4589212	KB4589212: Intel microcode updates for Windows 10, version 2004 and 20H2, and Windows Server, version 2004 and 20H2

April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5001404	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
KB5001407	KB5001407: Servicing stack update for Windows 10, version 1809: April 22, 2021
KB5001384	April 22, 2021-KB5001384 (OS Build 17763.1911) Preview

March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB4589208	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
KB5000859	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
KB5000822	March 9, 2021—KB5000822 (OS Build 17763.1817)

March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB5000802	March 9, 2021—KB5000802 (OS Builds 19041.867 and 19042.867)
KB4589208	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
KB5000859	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
KB5000854	March 25, 2021-KB5000854 (OS Build 17763.1852) Preview

March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4589208	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
KB5000859	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
KB5001638	March 18, 2021—KB5001638 (OS Build 17763.1823) Out-of-band

February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB4601555	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB4486153	Microsoft .NET Framework 4.8 on Windows 10 version 1709, Windows 10 version 1803, Windows 10 version 1809 and Windows Server 2019
KB4601393	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
KB4601345	February 9, 2021—KB4601345 (OS Build 17763.1757)

February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4601555	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB4577586	KB4577586: Update for the removal of Adobe Flash Player: October 27, 2020
KB4601393	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
KB4601383	February 16, 2021-KB4601383 (OS Build 17763.1790) Preview
KB4601050	February 9, 2021-KB4601050 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2
KB4601319	February 9, 2021—KB4601319 (OS Builds 19041.804 and 19042.804)

February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4601555	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB4577586	KB4577586: Update for the removal of Adobe Flash Player: October 27, 2020
KB4601393	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
KB4601383	February 16, 2021-KB4601383 (OS Build 17763.1790) Preview

January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
KB4598303	January 26, 2021-KB4598303 Cumulative Update Preview for .NET Framework 3.5 and 4.7.2 for Windows 10, version 1809 and Windows Server, version 2019
KB4486153	Microsoft .NET Framework 4.8 on Windows 10 version 1709, Windows 10 version 1803, Windows 10 version 1809 and Windows Server 2019
KB4535680	Security update for Secure Boot DBX: January 12, 2021
KB4580325	Security Update for Adobe Flash Player: October 13, 2020
KB4598480	Servicing stack update for Windows 10, version 1809: January 12, 2021
KB4598230	January 12, 2021-KB4598230 (OS Build 17763.1697)

January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4598300	January 26, 2021-KB4598300 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB4598480	Servicing stack update for Windows 10, version 1809: January 12, 2021
KB4598296	January 21, 2021-KB4598296 (OS Build 17763.1728) Preview

Microsoft Knowledge Base Article ID	Description
KB4535680	Security update for Secure Boot DBX: January 12, 2021
KB4598481	Servicing stack update for Windows 10, version 2004 and 20H2: January 12, 2021
KB4598242	January 12, 2021—KB4598242 (OS Builds 19041.746 and 19042.746)

January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
KB4598300	January 26, 2021—KB4598300 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
KB4598480	Servicing stack update for Windows 10, version 1809: January 12, 2021
KB4598296	January 21, 2021—KB4598296 (OS Build 17763.1728) Preview
KB4535680	Security update for Secure Boot DBX: January 12, 2021

This page is intentionally left blank.

Honeywell Building Technologies – Security Americas (Head Office)

Honeywell Commercial Security
715 Peachtree St. NE
Atlanta, GA 30308
www.security.honeywell.com/
☎ +1 800 323 4576

Honeywell Building Technologies – Security Mexico

Mexico: Av. Santa Fe 94, Torre A, Piso 1, Col. Zedec,
CP 0121, CDMX, Mexico.
Colombia: Edificio Punto 99, Carrera 11a.
98-50, Piso 7, Bogota, Colombia.
clarsupport@honeywell.com
☎ 01.800.083.59.25
www.honeywell.com

Honeywell Colombia SAS

Carrera 11A # 98-50
Edificio Punto 99, Piso 7, Bogotá DC
Colombia

Honeywell Building Technologies – Security Middle East/N. Africa

Emaar Business Park, Sheikh Zayed Road
Building No. 2, 2nd floor, 201
Post Office Box 232362
Dubai, United Arab Emirates
☎: +971 44541704
www.honeywell.com/security/me

Honeywell Building Technologies – Security Europe/South Africa

Aston Fields Road, Whitehouse Industrial Estate
Runcorn, WA7 3DL,
United Kingdom
www.honeywell.com/security/uk
☎ 08448 000 235

Honeywell Building Technologies – Security Northern Europe

Stationsplein Z-W 961,
1117 CE Schiphol-Oost, Netherlands
www.security.honeywell.com/nl
☎ +31 (0) 299 410 200

Honeywell Building Technologies – Security Deutschland

Johannes-Mauthe-Straße 14 72458 Albstadt, Germany
www.security.honeywell.de
☎ +49 (0) 7431 801-0

Honeywell Building Technologies – Security France

Immeuble Lavoisier
Parc de Haute Technologie 3-7 rue Georges Besse 92160 Antony, France
www.security.honeywell.com/fr
☎ +33 (0) 1 40 96 20 50

Honeywell Building Technologies – Security & Fire (Pacific)

Honeywell Ltd. 9 Columbia Way, BAULKHAM HILLS NSW 2153
Visit: www.honeywellssecurity.com.au. Email: hsf.comms.pacific@Honeywell.com
☎ Tech Support: Australia: 1300 220 345, New Zealand: +64 9 623 5050

Honeywell Building Technologies – Security Italia SpA

Via Achille Grandi 22, 20097 San Donato Milanese (MI), ITALY
www.security.honeywell.com/it

Honeywell Commercial Security - España

Josefa Valcárcel, 24
28027 - Madrid
España
www.honeywell.com
☎ +34 902 667 800

Honeywell Building Technologies – Security Россия и СНГ

121059 Moscow, UI, Kiev 7 Russia
www.security.honeywell.com/ru
☎ +7 (495) 797-93-71

Honeywell Building Technologies – Security Asia Pacific

Building #1, 555 Huanke Road,
Zhang Jiang Hi-Tech Park Pudong New Area,
Shanghai, 201203, China
www.asia.security.honeywell.com
☎ 400 840 2233

Honeywell Building Technologies – Security and Fire (ASEAN)

Honeywell International Sdn Bhd
Level 25, UOA Corp Tower, Lobby B
Avenue 10, The Vertical, Bangsar South City
59200, Kuala Lumpur, Malaysia
Visit Partner Connect: www.partnerconnect.honeywell.com
Email: buildings.asean@honeywell.com

Technical support (Small & Medium Business):

Vietnam: ☎ +84 4 4458 3369
Thailand: ☎ +66 2 0182439
Indonesia: ☎ +62 21 2188 9000
Malaysia: ☎ +60 3 7624 1530
Singapore: ☎ +65 3158 6830
Philippines: ☎ +63 2 231 3380

Honeywell Home and Building Technologies (India)

HBT India Buildings
Unitech Trade Centre, 5th Floor,
Sector – 43, Block C, Sushant Lok Phase – 1,
Gurgaon – 122002, Haryana, India
Visit Partner Connect: www.partnerconnect.honeywell.com
Email: HBT-IndiaBuildings@honeywell.com
Toll Free No: 1-800-103-0339
☎ +91 124 4975000

Honeywell Building Technologies – Security and Fire (Korea)

Honeywell Co., Ltd. (Korea)
5F SangAm IT Tower,
434, Worldcup Buk-ro, Mapo-gu,
Seoul 03922, Korea
Visit: <http://www.honeywell.com>
Email: info.security@honeywell.com
Customer support: HSG-CS-KR@honeywell.com; +82 1522-8779
☎ +82-2-799-6114



Document: Pro-Watch®_VMS_NVR – Microsoft Windows Patches – 12/2021

www.honeywell.com/security
+1 800 323 4576 (North America only)
<https://honeywellsystems.com/ss/techsupp/index.html>

www.honeywell.com/security/uk
+44 (0) 1928 754 028 (Europe only)
<https://honeywellsystems.com/ss/techsupp/index.html>