

# Pro-Watch<sup>®</sup> VMS and NVR

Approved Microsoft<sup>®</sup> Windows Patches



---

## Technical Notes

---

# MICROSOFT® WINDOWS PATCHES TESTED WITH PRO-WATCH® NVR AND VMS

## Overview

The purpose of this document is to identify the patches that have been delivered by Microsoft® Windows and which have been tested against the current shipping versions of Pro-Watch® NVR and Pro-Watch® VMS with no adverse effects being observed.

If you have questions concerning the information in this document, please contact Honeywell Technical Support. See the back cover for contact information.

**Windows Patches Tested with Pro-Watch® NVR till the Month of:** November, 2021

**Windows Patches Tested with Pro-Watch® VMS till the Month of:** November, 2021

**This document contains:**

Section	See...
<ul style="list-style-type: none"><li>• <i>November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2019 Standard</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Client on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>November - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Server on Windows 2019 Standard</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®VMS Client on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>October - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>
<ul style="list-style-type: none"><li>• <i>September - 2021- Microsoft® Windows Patches Tested with Pro-Watch®NVR on Windows 10 (Enterprise)</i></li></ul>	<i>page 6</i>

Section	See...
<ul style="list-style-type: none"> <li>• <a href="#">August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)</a></li> <li>• <a href="#">August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 8</a></p> <p style="text-align: right;"><a href="#">page 7</a></p> <p style="text-align: right;"><a href="#">page 7</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> <li>• <a href="#">July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 8</a></p> <p style="text-align: right;"><a href="#">page 8</a></p> <p style="text-align: right;"><a href="#">page 8</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)</a></li> <li>• <a href="#">June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 9</a></p> <p style="text-align: right;"><a href="#">page 9</a></p> <p style="text-align: right;"><a href="#">page 9</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 10 (Enterprise)</a></li> <li>• <a href="#">May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 10</a></p> <p style="text-align: right;"><a href="#">page 10</a></p> <p style="text-align: right;"><a href="#">page 10</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</a></li> <li>• <a href="#">April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 11</a></p> <p style="text-align: right;"><a href="#">page 11</a></p> <p style="text-align: right;"><a href="#">page 11</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</a></li> <li>• <a href="#">March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 12</a></p> <p style="text-align: right;"><a href="#">page 12</a></p> <p style="text-align: right;"><a href="#">page 12</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</a></li> <li>• <a href="#">February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 13</a></p> <p style="text-align: right;"><a href="#">page 13</a></p> <p style="text-align: right;"><a href="#">page 14</a></p>
<ul style="list-style-type: none"> <li>• <a href="#">January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard</a></li> <li>• <a href="#">January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)</a></li> <li>• <a href="#">January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)</a></li> </ul>	<p style="text-align: right;"><a href="#">page 14</a></p> <p style="text-align: right;"><a href="#">page 14</a></p> <p style="text-align: right;"><a href="#">page 15</a></p>

## Pro-Watch® NVR Current Shipping Version

- Pro-Watch® NVR Server and Client

<b>Build</b>	Pro-Watch® NVR 6.7 Build 687
<b>Operating System</b>	Microsoft® Windows 10, 64 bit (Standard) Enterprise Server + Client)
<b>SQL Version</b>	Microsoft® SQL Server 2017 (RTM-CU19) ( <a href="#">KB4535007</a> ) - 14.0.3281.6 (X64)

## Pro-Watch® VMS Current Shipping Version

- Pro-Watch® VMS Server and Client

<b>Build</b>	Pro-Watch® VMS R670 Build 687
<b>Operating System</b>	Microsoft® Windows 2019 Standard 64 bit for Server. Microsoft® Windows 10 Enterprise, 32-bit / 64-bit for Client
<b>SQL Version</b>	Microsoft® SQL Server 2017 (RTM-CU19) ( <a href="#">KB4535007</a> ) - 14.0.3281.6 (X64)

**Note:** Microsoft will no longer provide security updates or support for PCs with Windows 7.

## November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5007290</a>	November 19, 2021-KB5007290 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5007266</a>	November 22, 2021-KB5007266 (OS Build 17763.2330) Preview

## November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5007289</a>	November 19, 2021-KB5007289 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2, and Windows Version 21H1
<a href="#">KB5007253</a>	November 22, 2021-KB5007253 (OS Builds 19041.1387, 19042.1387, 19043.1387, and 19044.1387) Preview

## November - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5007290</a>	November 19, 2021-KB5007290 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5007266</a>	November 22, 2021-KB5007266 (OS Build 17763.2330) Preview

## October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5006366</a>	October 19, 2021-KB5006366 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5006744</a>	October 19, 2021—KB5006744 (OS Build 17763.2268) Preview

## October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005539</a>	October 12, 2021-KB5005539 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2, and Windows Version 21H1
<a href="#">KB5006670</a>	October 12, 2021—KB5006670 (OS Builds 19041.1288, 19042.1288, and 19043.1288)

## October - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5006366</a>	October 19, 2021-KB5006366 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5006744</a>	October 19, 2021—KB5006744 (OS Build 17763.2268) Preview

## September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005540</a>	September 21, 2021-KB5005540 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5005625</a>	September 21, 2021-KB5005625 (OS Build 17763.2210) Preview

## September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005565</a>	September 14, 2021-KB5005565 (OS Builds 19041.1237, 19042.1237, and 19043.1237)

## September - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005540</a>	September 21, 2021-KB5005540 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5005625</a>	September 21, 2021-KB5005625 (OS Build 17763.2210) Preview

## August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005112</a>	KB5005112: Servicing stack update for Windows 10, version 1809: August 10, 2021
<a href="#">KB5005030</a>	August 10, 2021—KB5005030 (OS Build 17763.2114)

## August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5004331</a>	August 10, 2021-KB5004331 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2, and Windows Version 21H1
<a href="#">KB5005033</a>	August 10, 2021—KB5005033 (OS Builds 19041.1165, 19042.1165, and 19043.1165)
<a href="#">KB5005260</a>	KB5005260: Servicing stack update for Windows 10, version 2004, 20H2, and 21H1: August 10, 2021

## August - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5005112</a>	KB5005112: Servicing stack update for Windows 10, version 1809: August 10, 2021
<a href="#">KB5005030</a>	August 10, 2021—KB5005030 (OS Build 17763.2114)



## July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5004332</a>	July 20, 2021-KB5004332 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5004424</a>	KB5004424: Servicing stack update for Windows 10, version 1809: July 20, 2021
<a href="#">KB5004308</a>	July 20, 2021-KB5004308 (OS Build 17763.2090) Preview

## July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003537</a>	July 13, 2021-KB5003537 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2, and Windows Version 21H1
<a href="#">KB5000736</a>	KB5000736: Featured update to Windows 10, version 21H1 by using an enablement package
<a href="#">KB5004237</a>	July 13, 2021-KB5004237 (OS Builds 19041.1110, 19042.1110, and 19043.1110)

## July - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5004332</a>	July 20, 2021-KB5004332 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5004424</a>	KB5004424: Servicing stack update for Windows 10, version 1809: July 20, 2021
<a href="#">KB5004308</a>	July 20, 2021-KB5004308 (OS Build 17763.2090) Preview

## June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003538</a>	June 15, 2021-KB5003538 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5003711</a>	KB5003711: Servicing stack update for Windows 10, version 1809: June 8, 2021
<a href="#">KB5003703</a>	June 15, 2021-KB5003703 (OS Build 17763.2028) Preview

## June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4023057</a>	KB4023057: Update for Windows 10 Update Service components
<a href="#">KB4052623</a>	Update for Microsoft Defender antimalware platform
<a href="#">KB890830</a>	Remove specific prevalent malware with Windows Malicious Software Removal Tool (KB890830)

## June - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003538</a>	June 15, 2021-KB5003538 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5003711</a>	KB5003711: Servicing stack update for Windows 10, version 1809: June 8, 2021
<a href="#">KB5003703</a>	June 15, 2021-KB5003703 (OS Build 17763.2028) Preview

## May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003255</a>	May 20, 2021-KB5003255 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5003243</a>	KB5003243: Servicing stack update for Windows 10, version 1809: May 11, 2021
<a href="#">KB5003217</a>	May 20, 2021-KB5003217 (OS Build 17763.1971) Preview

## May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003254</a>	May 25, 2021-KB5003254 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, Windows Server, version 20H2 and Windows 10 Version 21H1
<a href="#">KB4562830</a>	Feature Update through Windows 10, version 20H2 Enablement Package
<a href="#">KB5003173</a>	May 11, 2021-KB5003173 (OS Builds 19041.985, 19042.985, and 19043.985)

## May - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5003255</a>	May 20, 2021-KB5003255 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB5003243</a>	KB5003243: Servicing stack update for Windows 10, version 1809: May 11, 2021
<a href="#">KB5003217</a>	May 20, 2021-KB5003217 (OS Build 17763.1971) Preview

## April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5001404</a>	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
<a href="#">KB5001342</a>	April 13, 2021–KB5001342 (OS Build 17763.1879)

## April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5001404</a>	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
<a href="#">KB5001407</a>	KB5001407: Servicing stack update for Windows 10, version 1809: April 22, 2021
<a href="#">KB5001384</a>	April 22, 2021-KB5001384 (OS Build 17763.1911) Preview
<a href="#">KB4589212</a>	KB4589212: Intel microcode updates for Windows 10, version 2004 and 20H2, and Windows Server, version 2004 and 20H2

## April - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5001404</a>	KB5001404: Servicing stack update for Windows 10, version 1809: April 13, 2021
<a href="#">KB5001407</a>	KB5001407: Servicing stack update for Windows 10, version 1809: April 22, 2021
<a href="#">KB5001384</a>	April 22, 2021-KB5001384 (OS Build 17763.1911) Preview

## March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4589208</a>	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
<a href="#">KB5000859</a>	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
<a href="#">KB5000822</a>	March 9, 2021—KB5000822 (OS Build 17763.1817)

## March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB5000802</a>	March 9, 2021—KB5000802 (OS Builds 19041.867 and 19042.867)
<a href="#">KB4589208</a>	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
<a href="#">KB5000859</a>	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
<a href="#">KB5000854</a>	March 25, 2021-KB5000854 (OS Build 17763.1852) Preview

## March - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4589208</a>	KB4589208: Intel microcode updates for Windows 10, version 1809 and Windows Server 2019
<a href="#">KB5000859</a>	KB5000859: Servicing stack update for Windows 10, version 1809: March 9, 2021
<a href="#">KB5001638</a>	March 18, 2021—KB5001638 (OS Build 17763.1823) Out-of-band

## February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4601555</a>	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4486153</a>	Microsoft .NET Framework 4.8 on Windows 10 version 1709, Windows 10 version 1803, Windows 10 version 1809 and Windows Server 2019
<a href="#">KB4601393</a>	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
<a href="#">KB4601345</a>	February 9, 2021—KB4601345 (OS Build 17763.1757)

## February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4601555</a>	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4577586</a>	KB4577586: Update for the removal of Adobe Flash Player: October 27, 2020
<a href="#">KB4601393</a>	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
<a href="#">KB4601383</a>	February 16, 2021-KB4601383 (OS Build 17763.1790) Preview
<a href="#">KB4601050</a>	February 9, 2021-KB4601050 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10, version 2004, Windows Server, version 2004, Windows 10, version 20H2, and Windows Server, version 20H2
<a href="#">KB4601319</a>	February 9, 2021—KB4601319 (OS Builds 19041.804 and 19042.804)

## February - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4601555</a>	February 16, 2021-KB4601555 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4577586</a>	KB4577586: Update for the removal of Adobe Flash Player: October 27, 2020
<a href="#">KB4601393</a>	KB4601393: Servicing stack update for Windows 10, version 1809: February 9, 2021
<a href="#">KB4601383</a>	February 16, 2021-KB4601383 (OS Build 17763.1790) Preview

## January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server on Windows 2019 Standard

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4598303</a>	January 26, 2021-KB4598303 Cumulative Update Preview for .NET Framework 3.5 and 4.7.2 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4486153</a>	Microsoft .NET Framework 4.8 on Windows 10 version 1709, Windows 10 version 1803, Windows 10 version 1809 and Windows Server 2019
<a href="#">KB4535680</a>	Security update for Secure Boot DBX: January 12, 2021
<a href="#">KB4580325</a>	Security Update for Adobe Flash Player: October 13, 2020
<a href="#">KB4598480</a>	Servicing stack update for Windows 10, version 1809: January 12, 2021
<a href="#">KB4598230</a>	January 12, 2021-KB4598230 (OS Build 17763.1697)

## January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® VMS Server/Client on Windows 2016 Standard and Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4598300</a>	January 26, 2021-KB4598300 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4598480</a>	Servicing stack update for Windows 10, version 1809: January 12, 2021
<a href="#">KB4598296</a>	January 21, 2021-KB4598296 (OS Build 17763.1728) Preview

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4535680</a>	Security update for Secure Boot DBX: January 12, 2021
<a href="#">KB4598481</a>	Servicing stack update for Windows 10, version 2004 and 20H2: January 12, 2021
<a href="#">KB4598242</a>	January 12, 2021—KB4598242 (OS Builds 19041.746 and 19042.746)

## January - 2021- Microsoft® Windows Patches Tested with Pro-Watch® NVR on Windows 10 (Enterprise)

Microsoft Knowledge Base Article ID	Description
<a href="#">KB4598300</a>	January 26, 2021—KB4598300 Cumulative Update Preview for .NET Framework 3.5 and 4.8 for Windows 10, version 1809 and Windows Server, version 2019
<a href="#">KB4598480</a>	Servicing stack update for Windows 10, version 1809: January 12, 2021
<a href="#">KB4598296</a>	January 21, 2021—KB4598296 (OS Build 17763.1728) Preview
<a href="#">KB4535680</a>	Security update for Secure Boot DBX: January 12, 2021



This page is intentionally left blank.

## Honeywell Building Technologies – Security Americas (Head Office)

Honeywell Commercial Security

715 Peachtree St. NE

Atlanta, GA 30308

[www.security.honeywell.com/](http://www.security.honeywell.com/)

☎ +1 800 323 4576

## Honeywell Building Technologies – Security Mexico

Mexico: Av. Santa Fe 94, Torre A, Piso 1, Col. Zedec,

CP 0121, CDMX, Mexico.

Colombia: Edificio Punto 99, Carrera 11a.

98-50, Piso 7, Bogota, Colombia.

clarsupport@honeywell.com

☎ 01.800.083.59.25

[www.honeywell.com](http://www.honeywell.com)

## Honeywell Colombia SAS

Carrera 11A # 98-50

Edificio Punto 99, Piso 7, Bogotá DC

Colombia

## Honeywell Building Technologies – Security Middle East/N. Africa

Emaar Business Park, Sheikh Zayed Road

Building No. 2, 2nd floor, 201

Post Office Box 232362

Dubai, United Arab Emirates

☎: +971 44541704

[www.honeywell.com/security/me](http://www.honeywell.com/security/me)

## Honeywell Building Technologies – Security Europe/South Africa

Aston Fields Road, Whitehouse Industrial Estate

Runcorn, WA7 3DL,

United Kingdom

[www.honeywell.com/security/uk](http://www.honeywell.com/security/uk)

☎ 08448 000 235

## Honeywell Building Technologies – Security Northern Europe

Stationsplein Z-W 961,

1117 CE Schiphol-Oost, Netherlands

[www.security.honeywell.com/nl](http://www.security.honeywell.com/nl)

☎ +31 (0) 299 410 200

## Honeywell Building Technologies – Security Deutschland

Johannes-Mauthe-Straße 14 72458 Albstadt, Germany

[www.security.honeywell.de](http://www.security.honeywell.de)

☎ +49 (0) 7431 801-0

## Honeywell Building Technologies – Security France

Immeuble Lavoisier

Parc de Haute Technologie 3-7 rue Georges Besse 92160 Antony, France

[www.security.honeywell.com/fr](http://www.security.honeywell.com/fr)

☎ +33 (0) 1 40 96 20 50

## Honeywell Building Technologies – Security & Fire (Pacific)

Honeywell Ltd. 9 Columbia Way, BAULKHAM HILLS NSW 2153

Visit: [www.honeywellsecurity.com.au](http://www.honeywellsecurity.com.au). Email: hsf.comms.pacific@Honeywell.com

☎ Tech Support: Australia: 1300 220 345, New Zealand: +64 9 623 5050

## Honeywell Building Technologies – Security Italia SpA

Via Achille Grandi 22, 20097 San Donato Milanese (MI), ITALY

[www.security.honeywell.com/it](http://www.security.honeywell.com/it)

## Honeywell Commercial Security - España

Josefa Valcárcel, 24

28027 - Madrid

España

[www.honeywell.com](http://www.honeywell.com)

☎ +34 902 667 800

## Honeywell Building Technologies – Security Россия и СНГ

121059 Moscow, UI, Kiev 7 Russia

[www.security.honeywell.com/ru](http://www.security.honeywell.com/ru)

☎ +7 (495) 797-93-71

## Honeywell Building Technologies – Security Asia Pacific

Building #1, 555 Huanke Road,

Zhang Jiang Hi-Tech Park Pudong New Area,

Shanghai, 201203, China

[www.asia.security.honeywell.com](http://www.asia.security.honeywell.com)

☎ 400 840 2233

## Honeywell Building Technologies – Security and Fire (ASEAN)

Honeywell International Sdn Bhd

Level 25, UOA Corp Tower, Lobby B

Avenue 10, The Vertical, Bangsar South City

59200, Kuala Lumpur, Malaysia

Visit Partner Connect: [www.partnerconnect.honeywell.com](http://www.partnerconnect.honeywell.com)

Email: [buildings.asean@honeywell.com](mailto:buildings.asean@honeywell.com)

## Technical support (Small & Medium Business):

Vietnam: ☎ +84 4 4458 3369

Thailand: ☎ +66 2 0182439

Indonesia: ☎ +62 21 2188 9000

Malaysia: ☎ +60 3 7624 1530

Singapore: ☎ +65 3158 6830

Philippines: ☎ +63 2 231 3380

## Honeywell Home and Building Technologies (India)

HBT India Buildings

Unitech Trade Centre, 5th Floor,

Sector – 43, Block C, Sushant Lok Phase – 1,

Gurgaon – 122002, Haryana, India

Visit Partner Connect: [www.partnerconnect.honeywell.com](http://www.partnerconnect.honeywell.com)

Email: [HBT-IndiaBuildings@honeywell.com](mailto:HBT-IndiaBuildings@honeywell.com)

Toll Free No: 1-800-103-0339

☎ +91 124 4975000

## Honeywell Building Technologies – Security and Fire (Korea)

Honeywell Co., Ltd. (Korea)

5F SangAm IT Tower,

434, Worldcup Buk-ro, Mapo-gu,

Seoul 03922, Korea

Visit: <http://www.honeywell.com>

Email: [info.security@honeywell.com](mailto:info.security@honeywell.com)

Customer support: [HSG-CS-KR@honeywell.com](mailto:HSG-CS-KR@honeywell.com); +82 1522-8779

☎ +82-2-799-6114



### Document: Pro-Watch®\_VMS\_NVR – Microsoft Windows Patches – 11/2021

[www.honeywell.com/security](http://www.honeywell.com/security)

+1 800 323 4576 (North America only)

<https://honeywellsystems.com/ss/techsupp/index.html>

[www.honeywell.com/security/uk](http://www.honeywell.com/security/uk)

+44 (0) 1928 754 028 (Europe only)

<https://honeywellsystems.com/ss/techsupp/index.html>